LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, MICH. P.A.1970

FOR CORNERS OF -:	LOCATED IN -:	CORNER CODE NUMBER	
1. PUBLIC LAND SURVEY 32	T	E-13	ر ر
2. PROPERTY CONTROLL-32 ING IN SECTION	,T	E-13	-
3. MISCELLANEOUS PROPERTY IN SECTION	N. S., RE.		
4. LOT NO , RECO			
5. PRIVATE CLAIMS			REGISTER OF DEEDS STAMP AND FILING NUMBER
do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above (identified with circles on index code diagram—over) were, in a field survey on MARC. 7 27, 1923, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on March 29 1923, found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law:			
A. Description of original monument and accessories and/or subsequent restoration:			
B. Description of corner evide Found & IRON CORNER IS PART OF H	Rod Encased in Con	د .	maning content
C. Description of monument f	or corner and accessories	established to perpetuate loc	ating the position of the corner:
_	neased in Concrete		
. N.60° W. 15.74	" 8" Hickory	,	
N. 16° W. 13.70'	12" Hickory		
N. 60° E. 17.84'	10" B. Cherry	y	
N. 16° W. 13.70' N. 60° E. 17.84' S. 42° W. 4.24	5" Red Codar		
All distances to	مرمرو وكهوراث المتراسيان		
SIGNED BY		DATE	pr 2, 1903
SURVEYOR'S MICHIGAN RE	GISTRATION NO. 120	29	(SEAL)
FOR STATE AND UNITED ST	TATES AGENCIES:		
SEGNED BY	CHIEF OF SURVEY PARTY	DATE	
APPROVED AND SIGNED BY	·	DATE	
	MICHIGAN REGISTERED L	AND SURVEYOR	(SEAL)
			1 <