		ı.				V
-	corners in			ON CERTIFICATE 4, Mich. P.A. 1970		a de la companya de l
ror c				. 1	016 100 100 100 100 100 100 100 100 100	<u></u>
	Livingston	Located In:	Corner Cod		വ — — —	FILED 8 32
1. P	Public Land Survey	T R T R T R T R				15, M 651
	Property Controlling S	T R	<u></u>		C.# 195m	Final
	Miscellaneous S	TR_			ster of Deeds Stamp	& Eile Number
Р	roperty in Sec. S	T R	<u> </u>		Ster of Decas Stamp	a i ne manber
	ot No, Record				A B C D · E F	GHIJKLM
5. P	rivate Claims	у			2 6 5 4	3 - 2 - 1
	Darina Doga	Do	ecember 21	93	4 7 8 9	101112
•	Bryan Boss , in a	field survey on	······································	_ , 19	5	
n line	reby certify that under requirements 1 and 2 above were in confo	ormance with regulations	and rules therefore a	is required in the	6 18 17 16 7	15 14 3
Manag	nt manual of survey instructions gement or by a decree of a Court	t of Law and/or that the co	orner points mentioned	in lines 3, 4 and 5	8 19 20 21	22-23-24
	were in conformance with the roof Law; established, re-esta				9	
•	ssed below:				10 30 29 28	27-26-25
ИОТЕ	 Not more than 4 corners on this certificate. 	s, all in the same town	and range, may be	recorded	11 31 32 33	34 35 36
4. D	escription of original monur	ment and accessories	and/or subsequent.		13	
	Surveyed Feb.	10, 1869 by M	1. W. Bulock		•	
		Oak 20 in. D Oak 12 in. D		Lks. Lks.		
	Additional inform	ation on back.				
						-
. D	escription of corner evidence	be found and/or methor	d applied in restorir	ng or reestablishing c	orner:	
	Found 1 1/2" P 16.7 South of Road	ipe 2 feet ± Centerline St	Deep Raised rawberry La	.with 1/2" x ke Road in S	18" Rebar houlder of OF BRYAI BOS Land Su	N L.
				1	NO 2923	
D	escription of monument for Set 1 $1/4$ $^{\circ}$ x 3 (Livingston Co	6" Iron Pipe	with Brass		position of the corner	
	S75°W 36.90' S N45°W 77.70' S NW Corner Hous NE Corner Hous	Spike S/Side 3 se 76.5'SW'ly		Monum	ved by Living entation Pee ptember 8, 19	r Group

rveyor's Michigan License No. 29238

Date December 28, 1993