LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, MICH. P.A.1970

FOR CORNERS OF -: LCCATED IN -:	CORNER CODE NUMBER
FOR CORNERS OF -: LCCATED IN -: N. E. S., R. W	
and in Section	13, 14, 16
3. MISCELLANEOUS N. PROPERTY IN SECTION T. T. S., R. W.	
4. LOT NO, RECORDED PLAT	
5. PRIVATE CLAIMS	REGISTER OF DEEDS STAMP AND
	FILING NUMBER
I,	red as expressed below and in conformance with regulations instructions of the United States Department of the Interior, 'urthermore, that the corner points mentioned in lines 3, 4, found, recovered, restored, established or re-established
A. Description of original monument and accessories and/or sub	sequent restoration:
,	
B. Description of corner evidence found and/or method applied	in restoring or re-establishing corner:
13 - Found Small Boat Spike.	
14 - Found 3/4" Square Head Bolt.	
16 - Set halfway and on line between J-3 a	nd K-3.
TO SEE HEATWAY WHO ON THIS CONSON O'S C	
C. Description of monument for corner and accessories establish	
13 - Set 1" pipe 6" below road surface. S 58° W 40.20' 26" Walnut Spike and Tag	14 - 3/4" Square Head Bolt. N 54° W 54.01' 9" Ash Spike and Tag
N 66° W 58.63' 26" Walnut Spike and Tag N 32° E 21.25' 8" Wood Sign Post Spike	N 70° E 146.31' Twin 12" & 15" R. Oak and Tag (Spike and Tag)
N 65° E 42.00° 16" Walnut Spike and Tag	S 28° W 82.39' 21" Maple Spike & Tag S 81° W 111.82' 14" Maple Spike & Tag
16 - Set 4"x36" concrete monument with alu cap. No witnesses available. In floor of gravel pit.	ក្រាប់កា
SIGNED BY	DATE
SURVEYOR'S MICHIGAN REGISTRATION NO.	(SEAL)
FOR STATE AND UNITED STATES AGENCIES:	<u> ಆ ಆಯಾಗಿ ಅರ್ಥ ಬರು ಪ್ರವರ್ಷ ಪ್ರತಿಗಳ ಸಂಕರ್ಣ ಪರ್ವವಾಗಿ ಆರ್ಥ ಪ್ರತ್ನವಾಗಿ ಕೈ ಅವರ ಪ್ರವರ್ಷ ಪ್ರವರ್ಷ ವರ್ಷ ಪ್ರವರ್ಷ ಅವರು ಪ್ರ</u>
SIGNED BY	DATE
APPROVED AND SIGNED BY	DATE 12-19-79
MICHĪGĀN REGIBTERĒD LAND	(SEAL)