

MAR 17 2000

FILED

SECTION

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in
LIVINGSTON
(County)

Located in: GREEN OAK Corner Code #

- 1. Public Land Survey T 1N R 6E F-5
T _____ R _____
T _____ R _____
T _____ R _____
- 2. Property Controlling S _____ T _____ R _____
in Section S _____ T _____ R _____
- 3. Miscellaneous S _____ T _____ R _____
Property in Sec. S _____ T _____ R _____

9

1999 NOV 22 A 11:11

NANCY HAVILAND
REGISTER OF DEEDS
LIVINGSTON COUNTY, MI.
48843

ISC# 1143m

Register of Deeds Stamp and File Number

- 4. Lot No. _____, Recorded Plat _____
- 5. Private Claims _____

I, Bryan L. Boss, in a field survey on SEPT. 16, 1999
do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned
in lines 1 and 2 above were in conformance with regulations and rules therefor as required in the
current manual of survey instructions of the United States Department of the Interior, Bureau of Land
Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5
above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a
Court of Law; established, re-established, monumented, re-monumented, recovered, found as
expressed below.

NOTE: Not more than 4 corners, all in the same town and range, may be recorded
on this certificate.

	A	B	C	D	E	F	G	H	I	J	K	L	M
2	6	5	4	3	2	1							
3													
4	7	8	9	10	11	12							
5													
6	18	17	16	15	14	13							
7													
8	19	20	21	22	23	24							
9													
10	30	29	28	27	26	25							
11													
12	31	32	33	34	35	36							
13													

A. Description of original monument and accessories and/or subsequent restoration:


SET 1/4 POST AT AVERAGE DISTANCE
TAMARACK 12" S60°W 89LINKS

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

FOUND DNR MONUMENT IN WETLANDS IN GOOD SHAPE

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

FOUND DNR MONUMENT IN CONCRETE IN
WETLANDS
N75°E 16.98' SET SET REMON NAIL & TAG S FACE
10" ASH
S20°E 33.00' SET REMON NAIL & TAG SW FACE
10" ASH
S24°W 3.94' SET REMON NAIL & TAG E FACE OF
6" MAPLE
S85°W 17.02' SET REMON ANIL & TAG S FACE OF
12" ASH



P.A. 345 1990, APPROVED BY LIVINGSTON COUNTY
PEER GROUP ON 9-15-99, CO. REP JED

Signed by [Signature]
Surveyor's Michigan License No. 29238

Date NOV. 9, 1999