Filing Requirement of Act 74, Mich. P.A. 1970 For corners in ivingston Located In: County County	FILED	1		-	-	S &	Si						amont of Act 74 Mich D		
(County)		į	:		VIAVI	EROF	NOON HO	ABBH 9			,	.A. 1970	1		ivingston
1. Public Land Survey	- - -	***************************************	204403	AM 35	N. C.	DEED'S	MIY, MI						<u>I-12</u>	T R T R	,
2. Property Controlling S T R	mher	New	Eile	. £ 1	amr	S+2	de							S T R S T R	in Section
Property in Sec. S T R	·						.03				9131	ne.		S T R	Property in Sec.
4. Lot No Recorded Plat A B C D E F G H I J	KL	ıJ	<u>H</u>	G	F	E	D	<u>_c</u>	В	<u>A</u>	-			scorded Plat	


I. H. Lawrence O'Donnel In a field survey on Decmeber 21 . 19 93 do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

GLO survey in 1816 by Joseph Wampler set qr. sec post W. Oak 26 SO1W 2.40 1ks B. Oak 12 s49 1/2 E 2.07 1ks

(Additional historical data on back of sheet)



SURVEYS PERONESCOTTO

1993

COMMISSION

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Found 1" iron pipe as referenced in 1957 survey by atwell-Hicks.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Set 1-1/4 x 36" Iron pipe with brass cap 24" Mpale East 12.83' to nail w/flasher 18" Maple N70°W 26.84' to nail w/flasher 12" ash N50°W 13.11' to nail w/flasher 40" Maple N10°W 53.50' to nail w/flasher



Date December 23, 1993

Surveyor's Michigan License No.

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971

Approved by Livingston County Monumentation Peer Group November 6, 1993 AEVISED JAN., 1983

Civil Engineering • Surveying Planning • Environmental Services

ATWELL-HICKS, INC.

540 Avis Drive P.O. Box 2981 Ann Arbor, Michlgan 48106 313 994 4000 • FAX: 313 994 1599

RESEARCH SUMMARY

I-12, W 1/4 Corner Section 35, T1N, R6E

Found 1" Iron pipe in E-W fence line of the W 1/4 Corner location.

Original GLO survey notes reference set gr. section post in swamp form which a W. Oak 26 in dia bears S/W 2.40 lks and a B. Oak 12 in dia bears S49-1/2E 2.07 lks.

Earliest found reference to the corner was a March 5, 1957 survey by Atwell-Hicks, Inc. at which time a 1" Iron pipe was found.

Corner is referenced in a 1975 survey by Kostecke (which is not the actual corner); A 1975 survey by W.E. Co.; A 1979 survey by Roskelly & Jekabson; 1975 survey by W.E. Co.; 1976 survey Boss Engineering; 1982 survey by Boss Engineering; 1985 survey by Boss Engineering; 1992 survey by Boss Engineering.

A search of the county surveyor records did not provide any information on this corner. Records held by C. Garlock mad reference to a cedar stake in ditch marking the corner witnessed by E.m 12" S 49 1/2 E 121 lks., Isaac Teller County Surveyor in 1886.

A search of the area found no other irons. I conclude that this iron pipe marks the location of the W 1/4 corner Section 35, T1N, R6E.

