

## LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

]
1996 NOV 14 P 1: 20
NANCY HAVILAND REGISTER OF DEEDS LIVINGSTON COUNTY, MI. 48843
L.S.C.#578m  Register of Deeds Stamp & File Number
A B C D E F G H I J K L M  2 6 5 4 3 2 - 1  3 4 7 8 9 - 10 - 11 - 12  5 6 - 18 - 17 - 16 15 - 14 13  7 8 19 20 - 21 - 22 - 23 - 24  9 10 30 29 28 27 26 25 - 11  12 31 32 33 34 35 36 13  IOSCO
orner: e on A-9/C-9 line. of this sheet.
nosition of the corner:  1-1/4" X 36" iron pipe,  I ston Co. Monumentation  I careful and faithful  I corner.  November 11, 1996

FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1971
REVISED MAY 14 1975
REVISED JAN., 1983
REVISED JAN., 1983

## IOSCO TOWNSHIP, TOWN 2 NORTH, RANGE 3 EAST

B-9, NORTH 1/4 COR. SEC. 30 AND SOUTH 1/4 COR. SEC. 19.

FIELD: 9-30-1996 DARRELL D. HUGHES AND ASSOCIATES.

Corner not found, 12" corner post called for by Munsell in 1958 (P. 10) was not found nor witness trees. Many large trees in area, could not reconstruct Munsell ties. Munsell used this corner for measurements of the county drain East of this corner. There is no East/West occupation in this area, except for wood line to North. There is a N/S tree row and farm field division to the South with same owner East and West I recommend, to the peer group, reconstructing B-9 from the 1996 Garlock survey (P.11A). Garlock pro-rated the GLO distances which check within a foot of pro-rating the 1861 Fairchild's distances, but did not need to set the corner for his survey.

- 1825 Sylvester Sibley, U.S. Deputy Surveyor, "West between 19 and 30, 40.00 chains, set 1/4 section post". P.7
- 1861 Ezra Fairchilds, county surveyor, surveys in Section 19. P.8
- 1875 Miles Bullock, county surveyor, surveys Section 30. P.9
- 1958 Lyle Munsell corner witnesses, P.10
- 1996 Charlie Garlock survey in Section 19. P.11