MAR 1 7 2000

FILED

SEC	7	0	V	į
200		-	4	v

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

For corners in				1999 HAY	21	Δ 9: I	21			
LIVINGSTON - Located					NANCY HAVILAND REGISTER OF DEEDS					
1. Public Land Survey	T_3N_R_3E TR TR	<u>H 7</u>		LIVINGS	TON COI 48843	3N1 Y. T	<b>11.</b>			
2. Property Controlling S in Section S 3. Miscellaneous S Property in Sec. S	TR TR TR			.S.C#99		amp &	File Nur	nber		
4. Lot No, Recorded Plat_			, A	вср	E F	G H	ı j K	L M		
5. Private Claims  CHARLES E GARLOCK, in a field requirements of P.A. 74, Michigan P.A. of 19 conformance with regulations and rules therefunited States Department of the Interior, Burethat the corner points mentioned in lines 3, 4 Board of Land Surveyors or by a Decree recovered found as expressed below:  NOTE: Not more than 2 corners, all in the on this certificate.	I survey on APRIL 25  270, the corner points mentions as required in the current or Land Management or Land 5 above were in conform of a Court of Law; establish	21999_ do hereby state oned in lines 1 and 2 above manual of survey instruct by a decree of a Court of Lenance with the rules of the shed, re-established, more	ions of the aw and for a Michigan numented,	7 - 8 - 10 - 17 - 13 - 20 - 30 - 29	916	-15	-11142326	12-13-24-25-25-		
A. Description of original monument a GLO SURVEY DATED APRIL 15 GLO WITNESSES ELM 8-S2 B ASH 8-	nd accessories and/or su 5, 1825 BY S SIBL 2W-71.28' -S84½W-89.10'	bsequent restoration: .EY AND NONE OF	THE GLO WIT	131.—32 1 1	REMAI	N.	35	36-		

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:
FOUND ½" I. ROD 1 FT. NORTH OF NORTH EDGE OF ASPHALT AND ON LINE WITH SE AND SW SECTION CORNERS
AT ½ DISTANCE BETWEEN SAID SECTION CORNERS. RESET ½" I ROD WITH 1½" X 36" BREAKAWAY I. PIPE

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:
H 7: S¼ COR. SECTION 15, T3N-R3E HANDY TWP. LIV. CO. MI. RESET WITH 1½" X 36" BREAKAWAY

I. PIPE WITH LIV. CO. REMON CAP ON TOP #14762

N80E-92.69'-SP & TAG S/S 14" WILLOW N80W-89.10'-SP & TAG S/S 16" WILLOW NORTH-32.96'-1" X 36" I. PIPE W/LIV. CO. WITNESS CAP #14762 SOUTH-59.98'-1" X 36" I. PIPE W/LIV. CO. WITNESS CAP #14762 SOUTH-11'-C/L OF ASPHALT ROAD.

Signed by Market Bahr Surveyor's Michigan License No. 14762

Date MAY 1, 1999

