FILED

\*\*\*...

OCT 2 5 1993

CC	MA	AIS	SIC	N

Property in Sec.

## LAND CORNER RECORDATION CERTIFICATE

SEP 27 8 38 AM 193

COMMISSION for corners in	Filing Requirement of Act 74, Mi	ch. P.A. 197
	•	

NANCY HAVILAND REGISTER OF DEEDS LIVINGSTON COUNTY, MI 48843

Livingston (County)	Located In:	Corner Code ##
Public Land Survey	T 3N R 3E	K-13
	T R	
	T R	
	T R	
2. Property Controlling	S T R	
in Section	S T R	
3. Miscellaneous	S T R	·

Lis.c.#8mc

Register of Deeds Stamp & File Number

4.	Lot No, Recorded Plat	
5.	Private Claims	

1. Charles E Garlock, in a field survey on September 24 do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration: GLO witnesses to SW corner Sec. 36 T3N-R3E, Handy Twp. (K-13) Hick 5-N67E-29 lks.; Symore 7-N81%W-114 lks. /(Sycamore)

See reverse side for conner summary of research.

GLO notes dated: April 15, 1825, Sylvester Sibley

10 11 12

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner: Found PK spike from previous witnesses and surveys by Patrick L Benton and myself.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner: Reset with 1%" X 36" I. Pipe with Liv. Co. Monumentation cap in Mon Box at (-0.5') N45E-46.14'-face of Conc. post 15" dia.

N30E-90.98'-sp W/s U. Pole

S45E-38.13'-sp W/s U. Pole

N80W-192.85'-sp S/s 6" Sycamore

East-110.62'-NW cor. Sec. 1 T2N-R3E, Iosco'

North-0.5'±-ctr. Mason Rd.

July 21, 1993 APPROVED by Livingston County Monumentation Peer Group

Signed by

Surveyor's Michigan License No.

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971 REVISED MAY 14, 1975

REVISED JAH., 1983

SERVING LIVINGSTON COUNTY SINCE 1868

"BE Sure of Your Ground"

## CHARLES E. GARLOCK

PROFESSIONAL SURVEYOR 840 EAST DAVIS ROAD HOWELL, MICHIGAN 48843

July 12, 1993

OFFICE: (517) 546-3340 FAX: 517 546-2941

K -13: SW corner Section 36, Handy Twp. Liv. Co. MI

Did not find any old, old witness point present. Found PK spike set for corner in 1969 road survey by PL Benton, which matched witnesses to old School foundation and again used in 1986 survey for Iosco Twp. Found Iosco Twp. Sec. corner 110.62 ft. East (GLO = 89.76ft) and found PK is about 5 ft. $\pm$  East of centerline of road to NOrth. Sweep of the area found no additional irons. Location of corner was rebuilt by PL Benton from the occupation deed lines of the old School building. M W Bullock had a 1.67 ch. jog for the Iosco Twp. falling corner with the SW corner prior to 1906.

Charles E Garlock, PS



Found PK spike in Asphalt Road