4

| 60 E     |       | ON     |
|----------|-------|--------|
| 5- Beach | 4 8 4 | W 19 W |

## LAND CORNER RECORDATION CERTIFICATE

| Fo | r corners in  | Filing Require                   | ment of Act 74, Mich. P | A. 1970   |
|----|---|----------------------------------|-------------------------|---|
|    | Livingston<br>(County)  | Located In:                      | Corner Code =##         | NANC:   |
| 1. | Public Land Survey  | T 3N R 3E  T R R R  T R R R      | L-3                     | 2 16 -PH<br>P HAVILAND<br>ER OF DEED<br>ON COUNTY.<br>48843 |
|    | Property Controlling<br>in Section<br>Miscellaneous<br>Property in Sec. | S T R<br>S T R<br>S T R<br>S T R |                         | L.S.C.#542M  Register of Deeds Stamp & File Number          |
|    |   | Recorded Plat                    |                         | A B C D E F G H I J K L M                                   |


ICharles E Garlockin a field survey on \_ June 20 do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

Description of original monument and accessories and/or subsequent restoration:

GLO survey dated: April 15, 1825 by S Sibley DS GLO Witnesses: WO7-N81W-24 lks

W026-S65E-48 lks



Additional historical data on near of sheet

Description of corner evidence found and/or method applied in restoring or reestablishing corner: Found 1" X 12" Iron Pipe at -0.5



Description of monument for corner and accessories established to perpetuate locating the position of the corner: L-3: S 1/4 cor. Sec. 1 T3N-R3E, Handy Twp. Liv.Co. MI, reset I. Pipe with 1 1/4" X 36" breakaway I. Pipe with Liv.Co. REmon Brass cap on top. S45W-39.10'-sp & tag E/s 50" Oak N60W-68.79'-sp & tag S/s 14" Hickory N60W-57.35'-face steel 4" dia. post, marker for gas line

N50E-43.92'-sp & tag W/s U. Pole

N45E-93.55'-SW cor. enclosed wood porch S45E-52.65'-sp & tag W/s 54" Oak

Cor. on centerline Xing of Sharp & Hogback Rds.

| Signed by Challer The Sol | 2 |
|---------------------------|---|
| Signed by Children        |   |

June 21, 1996

Date ..

Surveyor's Michigan License No. .

P.A. 345 1990, APPROVED BY LIVINGSTON COUNTY PEER GROUP ON 3-27-96 CO. REP VED

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971 REVISED MAY 14, 1975 REVISED JAN., 1983