TSURVEY & REMONUMENTATION

FEB 2 5 1999

l	1	^	_	

SECTION LAND CORNER RECORDATION CERTIF Filing Requirement of Act 74, Mich. P.A.	ICATE 1970 ⊑ ፷ ≦జ. జ
LIVINGSTON Located In: Corner Code #	REGISTER VINGSTON
1. Public Land Survey	HAVILAND R OF DEEDS
2. Property Controlling S T R in Section S T R 3. Miscellaneous S T R Property in Sec. S T R	L.S.C.#846m
	Register of Deeds Stamp & File Number
4. Lot No, Recorded Plat 5. Private Claims	A B C D E F G H I J K L M
CHARLES E GARLOCK, in a field survey on JUNE 4, 19 98 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in United States Department of the Interior. Bureau of Land Management of survey instructions of the	
United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:	
NOTE: Not more than 2 comers, all in the same town and range, may be recorded on this certificate.	9 23 24 27 26 25 11
A. Description of original monument and accessories and/or subsequent restoration: GLO SURVEY DATED: APRIL 15, 1825 BY S SIBLEY, DS GLO WITNESSES: WO 11-N15E-50 LKS WO 8-N45½W-81 LKS.	12 31 32 33 34 35 36
ADDITIONAL DATA ON REAR OF SHEET	
B. Description of comer evidence found and/or method applied in restoring or reestablishing come FOUND %" I. ROD WITH FENCE LINES NORTH & SOUTH AND CENTERLINE	ner: OF ROADS SOUTH & WEST.
G7:	
C. Description of monument for corner and accessories established to perpetuate locating the pose COR. SEC. 21, T3N-R4E, HOWELL TWP. LIV. CO. MI, RESET FOUND AWAY I. PIPE WITH LIV, CO. REMON BRASS CAP ON TOP	名" I. ROD WITH 1½" X36" BREAK-
	EYOR S

14762

Surveyor's Michigan License No._