LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970 r corners in LIVINGSTON Located In: Corner Code ## Countyl T 3N R 5E L-03 Public Land Survey T____R_ L.S.C.#517m **Property Controlling** S ____ R _ in Section Miscellaneous Register of Deeds Stamp & File Number Property in Sec. ____ , Recorded Plat ___ Private Claims ___ October 10 Jack K. Smith 19 in a field survey on . hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned lines 1 and 2 above were in conformance with regulations and rules therefore as required in the rent manual of survey instructions of the United States Department of the Interior, Bureau of Land ■nagement or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 ove were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a urt of Law; established, re-established, monumented, re-monumented, recovered, found as pressed below: DTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate. Description of original monument and accessories and/or subsequent restoration: L-03 The North 1/4 Corner of Section 12, Oceola Township was set by the

N20°W

W. Oak 23" S52°E

10"

Description of corner evidence found and/or method applied in restoring or reestablishing corner:

. L-03 Found PK nail. See the remonumentation dossier for this corner for additional information.

NOTE: NONE OF THE ORIGINAL WITNESSES COULD BE FOUND OR PERPETUATED SEE THE BACK OF THIS SHEET FOR ADDITIONAL HISTORICAL DATA.

SURVEY & REMONUMENTATION

GLO in 1823 by S. Sibley. The original witnesses are:

W. Oak

NOV 27 1995

CONTAINON

SMITH PROFESSIONAL **SURVEYOR**

No.

Description of monument for corner and accessories established to perpetuate locating the position of the corner:

L-03 North 1/4 Corner, Section 12, T3N, R5E Set 30" x 1 1/4" iron pipe with 6" x 1 1/4" break-off section and brass cap marked as "Livingston County Monument Corner" in monument box 1.5' north of centerline

S50°E	Set 36" x 1" iron pipe with brass witness cap	54.07
N46°E	Set nail and tag in SE side 12" Elm	41.57'
N19°W	Set nail and tag in E side 14" Triple Apple	33.11'
S50°W	Found PK nail in top of square conc. pillar	42.96
S76°W	Set nail and tag in NW side 8" Oak	96.90'

October 10, 1995

∎veyor's Michigan Liçense No. .

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971 REVISED MAY 14, 1975

P.A. 345 1990, APPROVED BY LIVINGSTON COUNTY

REVISED JAN., 1983

45 lks (29.8')

14 lks (9.2')

T3N - R5E: North 1/4 Corner, Section 12, Oceola Township

We found a PK nail at the surface in the intersection of centerlines of Clyde Road and Musson Road to the south. The corner was originally recorded as being set by Sibley in 1823 for the GLO. The first recorded witnesses for the current corner that I could find was by Charles Garlock in 1987, in which he reports a PK nail over a large iron. Witnesses from that survey agree with witnesses by Brady, Hughes and Desine, and the distance to the centerline of a Private Road to the North agress with Kostecke measure of 1973. Current measure matches well with Hughes ('92), Finney ('81), Brady ('89) and Garlock ('93). Witnesses checked with Brady, Hughes and Garlock. The Bullock distance of 1878 to the east is within 0.2' and differs by 9 feet in measure to the west. A sweep of the area and differs by 9 feet in measure to the west. A sweep of the area near this location did not reveal any other corner markers. This corner is open and usable for GPS. I recommend accepting L-03, the North 1/4 Corner of Section 12, Oceola at the location as is presently monumented.

JACK K. SMITH
PROFESSIONAL
JACK K. SMITH, PS
Desine Inc.

No.
35999