nFC.	\mathbf{A}	7	1001


___ , Recorded Plat __

5. Private Claims _

LAND CORNER RECORDATION CERTIFICATE

o	r corners in	Filing Require	ement of Act 74, Mich. P.	.A. 1970 =	SEF	9
	LIVINGSTON MISSI	Located In:	Corner Code =##	HANGS:	<u> </u>	ভা
	Public Land Survey	T _3.N_ R _5E_ T R T R T R	-L-09	TER OF DECITION COUNTY 48843	8 58 AH	FILED
?. 5.	Property Controlling in Section Miscellaneous S Property in Sec.	T R T R T R		L.S.C.# 256m Register of Deeds Stamp &	File Nu	mber

. Jack K. Smith . in a field survey on August 17 . 19 94 .
do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned
In lines 1 and 2 above were in conformance with regulations and rules therefore as required in the
current manual of survey instructions of the United States Department of the Interior, Bureau of Land
"Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5
■bove were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a



NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

Court of Law; established, re-established, monumented, re-monumented, recovered, found as


- Description of original monument and accessories and/or subsequent restoration:
 - L-09 The North 1/4 Corner of Section 25, Oceola Township was set by the GLO in 1823 by S. Sibley.

The original witnesses are:

16" B. Oak N22.5W 19 lks W. Oak 10" N82W 40 lks

NOTE: NONE OF THE ORIGINAL WITNESSES COULD BE FOUND OR PERPETUATED SEE THE BACK OF THIS SHEET FOR ADDITIONAL HISTORICAL DATA.

- 3. Description of corner evidence found and/or method applied in restoring or reestablishing corner:
 - L-09 Found P.K. nail 1 foot ± north of the edge of concrete on M-59 on the easterly side of Musson Rd. The P.K. is at the midpoint of the North line of Section 25.



L-09 North 1/4 Corner, Section 25, T3N, R5E Set 36" x 1 1/4" iron pipe with brass cap marked as "Livingston County Monument Corner" N67°W 36" x 1" pipe with brass cap 57.631 36" x 1" pipe with brass cap N73°E 55.75'

36" \times 1" pipe with brass cap S42°E 57.21' 36" x 1" pipe with brass cap S57°W 82.29 S32°W Nail with tag E. side power pole 83.381 N41°W Nail/with tag E. side power pole

igned by

Date __September_8,_1994_

L-09 T3N - R5E: North 1/4 Corner, Section 25, Oceola Township

We found a PK nail 1 foot ± north of the edge of concrete on M-59 on the easterly side of Musson Road (gravel) as set by C. Garlock in 1983. The corner was originally recorded as being set by Sibley in 1823 for the GLO. There are no recorded Act 74s for this corner. The PK nail is at the midpoint of the North line of Section 25. We also found a 1/2" rerod 5.2 feet north and 10.14 feet west of the PK, but I could not find any references to its use and I beleive it may have been used as a traverse point to see up the road to the north. A sweep of the area near the PK and iron did not reveal any other corner markers. This corner is in a fairly open area but is in a dangerous location to occupy. I recommend accepting L-09, the North 1/4 Corner of Section 25, Oceola at the location as is presently monumented by the PK nail.

Jack K. Smith, PS

Desine Inc.

JACK K.
SMITH
PROFESSIONAL
SURVEYOR
No.
35999

10