FILED

LAND CORNER RECORDATION CERTIFICATE

For corners in	Filing Requiren	nent of Act 74, Mich. P.A. 1	970	JUN	10 1] 11	AH '	94		
Livingston (County)	Located in:	Corner Code ##		8	ANGY GISTEI	HAVII	# 43 F			
Public Land Survey	T _3 /\ R6 /\ E T R T R			LIVIN	6210)	l Çou 843	re e ara H∃Y, A	; 4 }		
 Property Controlling in Section Miscellaneous Property in Sec. 	T R S T R S T R S T R S T R			S.C.#1		Stamp	a & Fil	le Nur	nber	
	ecorded Plat			а в	C D	E F	G H	1 1 3	к	LĄ
do hereby certify that under require lines 1 and 2 above were in a current manual of survey instruct Management or by a decree of a cabove were in conformance with Court of Law; established, reexpressed below: NOTE: Not more than 4 conformance with certificate. A. Description of original manual survey in the certificate in the certificate in the certificate.	in a field survey onAugusticements of P.A. 74, Michigan P.A. of conformance with regulations and retions of the United States Departmetourt of Law and/or that the corner perfect the rules of the Michigan Board of Lestablished, monumented, re-monumers, all in the same town and conument and accessories and/or accessories a	1970, the corner points mentioned rules therefore as required in the ent of the Interior, Bureau of Land soints mentioned in lines 3, 4 and 5 and Surveyors or by a Decree of a numented, recovered, found as range, may be recorded	. 5 1 6 7	3 -19 30 30 31 22 31 -	20-29-32-32-	-21- -28- -33-	15	2	3-6	-121324
GLO Notes dated: GLO Witnesses:	April 5, 1823 Hickory 10" 55°W 35 LI W. Oak 30" N64°E 60 LI									

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Found no evidence of Section Corner of previous witnesses. Set Section corner from a previous survey by Boss Engineering. Boss witnesses from previous survey and Garlock witnesses are in agreement

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

NE CORNER SEC 1, T3N-R6E

Set 1 1/4" x 72" Solid Iron Pipe with Brass Cap (Liv. Co. Monument Cor.) in Swamp N45°W 50.25' to 1 1/4" x 72" Iron Pipe with Brass Witness Cap N45°E 57.50' to 1 1/4" x 72" Iron Pipe with Brass Witness Cap S 45°E 64.28' to 1 1/4" x 72" Iron Pipe with Brass Witness Cap S 45°W 60.48' to 1 1/4" x 72" Iron Pipe with Brass Witness Cap

Approved By Livingston County OF MICKE Monumentation Peer Group

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN 28, 1971 REVISED MAY 14, 1975 REVISED JAN , 1983



EDWARD E. ANDERSON, P.S., P.E. RICHARD F. FRANK, P.S. BRIAN R. SHALTZ, C.S.T.

Members of: Michigan Society of Professional Surveyors American Congress on Surveying and Mapping American Society of Civil Engineers

401 S. Leroy St. Fenton, Michigan 48430-2164

(313) 629-8974 FAX (313) 629-9069

October 13, 1993

Broken

SE CORNER, SECTION 36, T4N-R6E, TYRONE TOWNSHIP, M - 13LIVINGSTON COUNTY, MICHIGAN.

Found nothing at location of SE corner said Section 36.

Boss and Garlock showed the same witnesses to said SE corner, Pages 6B, 7B, 8B, 14, and 15 this dossier. I was unable to find any of these witnesses.

Distance from SE corner to S 1/4 Corner of said 36 was 2679.52 per Boss, Page 6A, this dossier, and 2656.50 per Garlock, Page 12 this dossier. Distance from SE corner to East 1/4 corner was 2672.21 per Boss, Page 6A and 2713.59 per Garlock Page 13 this dossier.

Old fence to North. Starts at North edge of swamp about 300 + North of Boss location of said SE corner and runs to the North. Found no occupation to East, West, or South. Corner falls in middle of swamp.

Made a clean sweep of area and found no irons.

Came to the conclusion that the best location for the said SE corner of said Section 36 would be at the location per Boss survey, Page 6A this dossier. We will set this corner at this location (per peer group approval) after the ground has frozen. We are unable to do so until then because of high water and boggy conditions inhibiting us from accurately setting the corner until the swamp has frozen over.

See Page 16 this dossier as to how we found the location of SE corner of said Section 36 per Boss Survey Page 6A, this dossier.

> Edward E. Anderson

P. S. #11495

NOTE: Corner #M-13 T4N-R6E, Tyrone Twp. and Corner M-1 T3N-R6E, Hartland Twp., are common corners and have been accepted and approved by the Peer

Group as such.

Architectural, Construction, Property and Drainage Surveys Civil Engir ing • Land and Sit = ng • Mortgage Insp. fon Reports