SURVEY & REMONUMENTATION

REMONUMENTATION CORNER UNDER ACT 345, MICHIGAN PUBLIC ACTS OF 1990

K	APR 2 8 1995		R RECORDATION CER		Nov	· Service Service Serv
or corners in LIVINGSTON	COMMISSIC	N ated In:	ment of Act 74, Mich.	P.A. 1970	NANCY HIEGISTER 1488	(GETLE
■. Public Land Surve	τ. τ.		J-13	·	AVILAND OF DEEDS COUNTY, HI	.
Property Controllingin SectionMiscellaneousProperty in Sec.	S T . S T .	R R		L.S.C.#	282m Deeds Stamp & File	Number
				2 6-3	C D E F G H	1 J K L M
-o hereby certify that und Ilines 1 and 2 above w Interest manual of survey Janagement or by a decr Dove were in conforman Out of Law; establish ressed below: -OTE: Not more that on this certific Description of orig "West 40.00 White (White (in a field sunder requirements of P. Avere in conformance vinstructions of the Uree of a Court of Law and ce with the rules of the led, re-established, in 4 corners, all in the cate.	A. 74, Michigan P.A. o with regulations and nited States Department of the corner of the Michigan Board of monumented, re-moderate town and accessories and 1/2 mile post W 3 9!!	f 1970, the corner points men rules therefore as required nent of the Interior, Bureau o points mentioned in lines 3, 4 Land Surveyors or by a Decronumented, recovered, four dirange, may be recorded for subsequent restoration.	tioned 6 18- in the f Land 7 land 5 8 19- ee of a 9 nd as 10 30- 11 12 31- 13 13		11 12 13 14 13 14 15 15 15 15 15 15 15 15 15 15 15 15 15
Found 3/4" :	solid iron rod	l	oplied in restoring or rees	v)	DONAL DONAL LAND SURVEY PAGE 14 TO LAND	ARDS *
Eorner" and "24 5 60 W 67.15' n 5 55 E 46.21' n N 45 E 72.63' n NORTH 33.88' ns tags read "Linstamped "24614"	4614" hail/tag* in s hail/tag* in n hail/tag* in s ail/tag*in wes vingston Count	outheast side fortheast side fouth side 9" at side 12" hi by Survey With	e 14" oak maple ickory		of the corner: Monumentation	n

P.A. 345 1980, APPROVED BY LIVERS FOR POLICE STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971
REVISED MAY 14, 1975
PEER GROUP ON 2/6074 CO. REP 10/6 L.
REVISED JAN., 1983

Date ..

24614

rveyor's Michigan License No.

November 1, 1994

(approved by peer group 9-21-94)

CONWAY J-13

This standard corner was established by Deputy Surveyor Joseph Wampler on February 14th, 1824. In the preparation of this report, we did not find any County Surveyors records pertaining to this corner.

Contemporary surveys at this corner identify the material as a 5/8" iron rod and, with minor variations in the estimated diameter, this description can be traced back to a survey by Charles E. Garlock in 1976. Garlock recorded this work as CLS 1835 and LSC 976 and all three of the witnesses he provided can still be found at this site. Moreover, subsequent surveys by Miller '84 and '86, and by Desine '91 incorporate two of Garlock's witnesses.

In 1976, the closing corner J-1 for T3N-R3E was recorded as a 1/2" iron bar in CLS 1894, 1895, and 1896 by Oscar Boss. The same identification can be found on CLS 2874 by Gary Boss in 1980, CLS 5191 by Darrell Hughes in 1981, and by A.F. Miller on CLS 4585 in 1990. A great many of the witnesses from these six surveys can still be recovered at this location.

On August 13th, 1994, this point was recovered by fieldcrews as a solid 3/4" iron. The point lies on the centerline of an east/west running gravel road, and in line with a tree row to the north. A 1/2" iron rod denoting the adjacent closing corner was recovered some 96.07' to the east, although this point appears to lie 0.61' North of the township line J-13 to K-13.

Donald G. Richards PS 24614 September 19th, 1994

to but appearable du