

STATE OF MICHIGAN
DEPARTMENT
OF
NATURAL RESOURCES
LAND CORNER RECORD


Mackinac COUNTY
T 41N R 11W

DESCRIPTION OF CORNER 1/4 corner bet. Secs. 4-5

CORNER MONUMENT 1" pipe with 4" aluminum cap.

DATE MONUMENT PLACED AND WITNESSED 4-17-69

WITNESSES TO CORNER..... 8" Hard Maple (1/4 S NBT) N1°E 15.1'



15" Hard Maple (1/4 S NBT) N83°W 21.0'

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner replaced on an old line of blazes from west. Found a 12" Hard Maple blazed on four sides, 10' east of Cor.
Corner lies 50' west of
Center line of road.

SURVEYOR'S SEAL

SIGNED

Billy D. Buckler
Billy D. Buckler
REGISTERED LAND SURVEYOR

DATE

5-2-69

DISTRIBUTION:

County Courthouse
Area Forester (Regions I & II)
District or Region Surveyor
Forestry Div., Lansing

R 4047
Rev. 10/68