

STATE OF MICHIGAN
DEPARTMENT
OF
NATURAL RESOURCES

LAND CORNER RECORD

Mackinac COUNTY


T 41N R 11W

DESCRIPTION OF CORNER Sec. Cor. common to Secs. 2-3-10-11

CORNER MONUMENT 1" Iron Pipe

DATE MONUMENT PLACED AND WITNESSED 6/25/69

WITNESSES TO CORNER..... 9" B. Ash (sll MBT) S76°E 31.6'



Boulder 4' high S45°E 5.1'

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

Recorded this corner as placed by unknown Land Surveyor. Found 1" iron pipe.
in place with original Tamarack bearing tree to north-west, in proper position
from the corner.

Corner lies in a N+S fence line.

SURVEYOR'S SEAL

Billy D. Buckler

SIGNED

Billy D. Buckler

DATE

6/25/72

DISTRIBUTION:

REGISTERED LAND SURVEYOR

County Courthouse
Area Forester (Regions I & II)
District or Region Surveyor
Forestry Div., Lansing

R 4047
Rev. 10/68