

STATE OF MICHIGAN
DEPARTMENT
OF
NATURAL RESOURCES

LAND CORNER RECORD

Mackinac COUNTY


T 41N R 11W

DESCRIPTION OF CORNER 1/4 Cor. bet. Secs. 5-6

CORNER MONUMENT 1" pipe with 4" aluminum cap

DATE MONUMENT PLACED AND WITNESSED 7-13-71

WITNESSES TO CORNER..... 9" Soft Maple (1/2 S NBT) N25°W 33.2'



9" Soft Maple (1/2 S NBT) S46°W 45.0'

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner re-established midway and on line between two Sec. Corners.
Found no evidence of original corner.

Found a line of blazes, running east from corner.

SURVEYOR'S SEAL

SIGNED

Billy D. Buckler
REGISTERED LAND SURVEYOR

DATE 7-26-71

DISTRIBUTION:

County Courthouse
Area Forester (Regions I & II)
District or Region Surveyor
Forestry Div., Lansing ✓

R 4047
Rev. 10/68