

STATE OF MICHIGAN  
DEPARTMENT  
OF  
NATURAL RESOURCES  
LAND CORNER RECORD

Mackinac COUNTY


T 41N R 11W

DESCRIPTION OF CORNER Sec. Cor. common to Secs. 5-6-7-8

CORNER MONUMENT 1" pipe with 4" aluminum cap

DATE MONUMENT PLACED AND WITNESSED 7-13-71

WITNESSES TO CORNER..... 7" Cedar (S5 NBT) N53°E 33.6'



6" Cedar (S8 NBT) S50°E 13.2'

8" Cedar (S7 NBT) S 64° W 13.5'

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

Corner replaced at an old cedar post, set by unknown surveyor. Found no evidence of original corner or witnesses.

Corner lies on a low ridge, in Cedar swamp.

SURVEYOR'S SEAL

SIGNED

*Billy D. Buckler*  
Billy D. Buckler

DATE

7-26-71

DISTRIBUTION:

REGISTERED LAND SURVEYOR

County Courthouse  
Area Forester (Regions I & II)  
District or Region Surveyor  
Forestry Div., Lansing ✓

R 4047  
Rev. 10/68