LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, MICH. P.A.1970

Mackinac Co.

1 Corner

| | OCATED IN -: | CORNER CODE NUMBER | |
|--|-----------------|--------------------|---|
| 1. PUBLIC LAND SURVEY T. | 11 N., R. 11 W. | D- 3 | |
| 2. PROPERTY CONTROLL- ING IN SECTION———, ,T., | N. S., R. W. | | |
| 3. MISCELLANEOUS PROPERTY IN SECTION, T | N. S., R E. | | |
| 4. LOT NO, RECORDED PLAT | | | |
| 5. PRIVATE CLAIMS | | | REGISTER OF DEEDS STAMP AND FILING NUMBER |

- A. Description of original monument and accessories and/or subsequent restoration:
- D-3 South 1/4 corner of Section 5. O.E.T.'S. Wood Post, Tamarack 4", N47 E, 47 lks. W. Pine 8", N20°W, 33 lks.
 - B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:
- D-3 Corner set from one original bearing tree, 8" W. Fine stump, N20°W, 21.78'. Lower face plain with scribe marks visible.
 - C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:
- D-3 D.N.R. Monument. New Learings: 8" Cedar, N4°E, 21.3' & 14" W. Pine, S64°E, 13.6' & 6" Cedar, S10°W, 28.8' & 6" Cedar, North, 18.9', Original 8" W. Pine, N20°W, 21.78'.

SIGNED BY David B. Babbitt DATE 3-3-83

SURVEYOR'S MICHIGAN REGISTRATION NO. 21558

(SEAL)