Cons. 4047 4/95

## MICHIGAN DEPARTMENT OF CONSERVATION FORESTRY DIVISION

## LAND CORNER RECORD

T\_41 NR\_12\_W

			-	WWCKTES	ī ā	COUNTY
DESCRIPTION	N OF	CORNER	Meander corner	for Sections	1 and 2	
DESCRIPTION	OF	CORNER	MONUMENT	1" Pipe with	4"_Brass_Ca	<b>P</b>
WITNESSES	то	CORNER _	9" Cedar	(M.C. NBT)	_S_24° E	46 1/2 <u>Links</u>
			7" Cedar	(M.C. NBT)	_ s_ 41° w _	54 Links
			8" Soft Maple	_(M_CNet) _	_ N 80° R	31 Links

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED. This corner was replaced from two Pine B.T. is bearing N 46° W, 79 Links in excellent condition (notes indicate this bearing to be N 26° E) and N 85° E 38 Links. Low stump with B.T. Corner found by Forestry Division Survey Crew.

Corner was placed and witnessed August 29, 1960 with Frank J. Bray.

SURVEYORS SEAL

SIGNED Suchler DATE 9/15/60 \_\_
REGISTERED LAND SURVEYOR
BITTY D. Buckler