

MICHIGAN  
DEPARTMENT OF CONSERVATION  
FORESTRY DIVISION

LAND CORNER RECORD

T 41-42 NR 12 W

Mackinac COUNTY

DESCRIPTION OF CORNER 1/4 corner between Sections 2 and 35

DESCRIPTION OF CORNER MONUMENT 1" Pipe with 4" Brass Cap

WITNESSES TO CORNER 6" Twin Hard Maple (1/4s NBT) N 15° E 01 Links

6" Hard Maple (1/4s NBT) S 54° W 39 Links

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED. This corner was re-established midway and on line between two section corners. No evidence of original corner.

Corner was placed and witnessed August 30, 1960.

SURVEYORS SEAL

SIGNED Billy D. Buckler DATE 9/15/60  
REGISTERED LAND SURVEYOR  
Billy D. Buckler