MICHIGAN DEPARTMENT OF CONSERVATION

FORESTRY DIVISION

LAND CORNER RECORD

T 41 NR 12 W

				Macki	n a c	COUNT
DESCRIPTION	OF	CORNER	1/4_corper	between Section	ms_2_and_3	
DESCRIPTION	OF	CORNER	MONUMENT	l" Pipe wi	ith_4"_Brass_C	ap
WITNESSES	то	ORNER .	10" W. Pin	. (1/4s NBT)	S_47°_B_	_48_1/2 I4nks
			_14* Red Pi	ne (1/4a NBT)	<u> </u>	_ 50 1/2 Links

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED. This corner was replaced from one Cedar B.T. bearing N 35° E 09 Links

Tree down and in poor condition. Found overgrowth in scribe marks of both faces and notch. Distance south to Meander Corner is 2.12 chains. Record distance = 2.10 chains. Scribed 5° Cedar (1/4s) at corner.

Corner was placed and witnessed August 31, 1960 with Frank J. Bray. SURVEYORS SEAL

SIGNED Silly D. Suchles

REGISTERED LAND SURVEYOR

BLILLY D. Buckler