

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T~~41-42~~ NR 11-12 W

Mackinac COUNTY

DESCRIPTION OF CORNER Section corner common to Section 1, 6, 36, 31 also
a Township Corner.
DESCRIPTION OF CORNER MONUMENT 1" Pipe with 4" Brass Cap
WITNESSES TO CORNER 15" W. Pine (S 31 NBT) N 50° E 38 1/2 Links
4" Cedar (S 6 NBT) S 15° E 84 Links
5" Cedar (S 36 NBT) N 30° W 60 Links

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR
RESTORED. This corner was replace at old wood post. Position checks well with calls of
record notes and corners in all directions. Corner lies in ditch on north side of road.

Corner was placed and witnessed August 30, 1960.

SURVEYORS SEAL

SIGNED

Billy D. Buckler
REGISTERED LAND SURVEYOR

Billy D. Buckler

DATE 9/15/60