

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T. ~~41~~ 42 NR. 12 W

M a c k i n a c COUNTY

DESCRIPTION OF CORNER Section corner common to Sections 2, 3, 34, 35

DESCRIPTION OF CORNER MONUMENT 1" Pipe with 4" Brass Cap.

WITNESSES TO CORNER 9" Soft Maple (S 34 NBT) N 52° W 42 Links

11" Hemlock (S 3 NBT) S 28° W 15 Links

8" Hemlock (S 35 NBT) East 06 Links

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED. This corner was established from possible B.T.s a Birch stump N 55° E 70 Links and Hemlock stump bottom N 38° W 65 Links. Position checks to ravine 1.50 chains to North. Found numerous old blazes at corner.

Corner was placed and witnessed May 25, 1960 with Frank J. Bray.

SURVEYORS SEAL

SIGNED

Billy D. Buckler
REGISTERED LAND SURVEYOR
Billy D. Buckler

DATE 8/11/60