

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T. 41-42N N.R. 12W


Mackinac COUNTY

DESCRIPTION OF CORNER 1/4 Corner bet. Secs. 3-34

CORNER MONUMENT 1" pipe with 4" aluminum cap.

DATE MONUMENT PLACED AND WITNESSED 12-21-70

WITNESSES TO CORNER..... 8" Cedar (1/2 S NBT) N37°W 120'



7" Cedar (1/2 S NBT) N51°E 19.6'

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner re-established, midway and on line between two section corners.
Found no evidence of original corner.
Found blazes along line to east and west.

Corner lies in a thick cedar swamp.

SURVEYOR'S SEAL

Billy D. Buckler
SIGNED Billy D. Buckler DATE 1-21-71
REGISTERED LAND SURVEYOR