

**LAND CORNER RECORDATION CERTIFICATE**  
**Filing Requirement of Act 74, Mich. P.A. 1970**

For corners in Mackinac Located In: \_\_\_\_\_ Corner Code # \_\_\_\_\_  
 (County)

1. Public Land Survey T 41N R 4W \_\_\_\_\_ D-1  
 T \_\_\_\_\_ R \_\_\_\_\_  
 T \_\_\_\_\_ R \_\_\_\_\_  
 T \_\_\_\_\_ R \_\_\_\_\_
2. Property Controlling S \_\_\_\_\_ T \_\_\_\_\_ R \_\_\_\_\_  
 In Section S \_\_\_\_\_ T \_\_\_\_\_ R \_\_\_\_\_
3. Miscellaneous S \_\_\_\_\_ T \_\_\_\_\_ R \_\_\_\_\_  
 Property in Section S \_\_\_\_\_ T \_\_\_\_\_ R \_\_\_\_\_
4. Lot No. \_\_\_\_\_, Recorded Plat \_\_\_\_\_
5. Private Claims \_\_\_\_\_

**RECEIVED & FILED**  
**DIANE FRANKOVICH**  
 MACKINAC COUNTY REGISTRE.. OF DEEDS

NOV 15 1996  
 AM \_\_\_\_\_ PM \_\_\_\_\_  
 7|8|9|10|11|12|1|2|3|4|5|6

Register of Deeds Stamp & File Number

I, David B. Guthrie on a field survey on May 15, 1996, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Professional Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

**NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.**

A	B	C	D	E	F	G	H	I	J	K	L	M
2	6	5	4	3	2	1						
3												
4	7	8	9	10	11	12						
5												
6	18	17	16	15	14	13						
7												
8	19	20	21	22	23	24						
9												
10	30	29	28	27	26	25						
11												
12	31	32	33	34	35	36						
13												

A. Description of original monument and accessories and/or subsequent restoration:  
 No record of this corner being set at the time of the G.L.O. Survey.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:  
 1996: Found 3/4" Iron Rod in a Monument Box at the intersection of the East West Road and a Road South.

**SURVEY & REMONUMENTATION**  
 MAY 20 1997  
**COMMISSION**

ACCEPTED BY THE MACKINAC COUNTY SURVEY PEER GROUP AS THE OFFICIAL CORNER UNDER P.A. 345 OF 1990 AT A MEETING HELDON 0-20-96

*James H. Granger*

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

1996: Placed an Aluminum Cap stamped to identify the corner on a 5/8" Iron Rod in a Monument Box.  
 Referenced: S50°W - Utility Pole - 47.60 Feet  
 S12°W - Stop Sign Post - 45.12 Feet  
 N35°E - S.W. Cor. Church - 66.19 Feet  
 S42°W - N.E. Cor. Hse. - 77.45 Feet  
 West - 1/2" Iron in Mon. Box - 30.34 Feet



Signed by David B. Guthrie Date Oct. 2, 1996  
 Surveyor's Michigan License No. 22435