MAD 1 9 1000

	MAK T 9 13:	MACKINAC COUN	TY REMONUMENTAT	ION CORNER
	SECTION		R RECORDATION CERTIFIC	
For corne	ers in	Filing Require	ement of Act 74, Mich. P.A. 1	mechina a zitku
	Mackinac (County)	Located In:	Corner Code ##	DIANE FRANKONOH
1. Public	c Land Survey	T <u>41N R 3W</u> T R	A-11 Sec Cor common to Sec's 30 & 31	DEC 29 1997 AM PAN 71819111121212141413141516
in Sec 3. Misce		S T R S T R S T R S T R	M-11, Sec Cor common to Sec 8 25 & 26	Register of Deeds Stamp & File Number
		ecorded Plat		A B C D E F G H I J K L
in lines 1 a current ma Manageme above were	certify that under req and 2 above were in nual of survey instru- ent or by a decree of a in conformance wit aw; established, r	in a field survey on	d rules therefore as required in the ment of the Interior, Bureau of Land r points mentioned in lines 3, 4 and 5 f Land Surveyors or by a Decree of a	e d 7 d 18 17 16 15 14 13 5 5 8 19 20 21 22 23 24 8 8 9 10 30 29 28 27 26 25
	lot more than 4 con this certificate.	orners, all in the same town an	d range, may be recorded	11 12 31 32 33 34 35 36
1845	GLO notes	er being perpetuated, howev	"Cedar S84W 75 lks	8
в. Des <i>ci</i> 1997	ription of corner ex Found 1" iron 4" W. Rirch	vidence found and/or method a	pplied in restoring or reestablis	shing corner:

3" W. Birch 40.04' (Face) S60E 5" Cedar **S80W** 66.2' (Face)

3" W. Birch N45W 56.75' Accepted corner location.

Found "T"-iron 220.30' West of Section Corner at Mackinac Trail R.O.W.

ACCEPTED BY THE MACKINAC COUNTY SURVEY PEER GROUP AS THE OFFICIAL CORNER UNDER PA. 345 OF 1990 AT A MEETING HELD ON 12-12-97

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Set %" rerod with remonumentation cap inside found pipe.

6" W. Birch N60E 5" W. Birch

45.98' (Side nail) 40.56' (Side nail) 66.38' (Side nail)

6" Cedar

S60E

S80W

N45W 36.84' (Side nail) 5" W. Birch



DECEMBER 22, 1997

Mill 27447