## LAND CORNER RECORDATION CERTIFICATE

## FILING REQUIREMENT OF ACT 74, MICH. P.A.1970

Mackinac Co.

SURVEYOR'S MICHIGAN REGISTRATION NO.

3 Corners.

F	OR CORNERS OF -:	LOCATED IN -:	CORNER CODE NUMBER	
1	. PUBLIC LAND SURVEY	T. 42 N. R. 1 E.	K-5, H-12, I-9	
2	PROPERTY CONTROLL- ING IN SECTION——	N. E. T S., R W.		
3	MISCELLANEOUS PROPERTY IN SECTION	,T N. R E.		
4	LOT NO, RECO			
5	, PRIVATE CLAIMS	· · · · · · · · · · · · · · · · · · ·		REGISTER OF DEEDS STAMP AND FILING NUMBER
I	Billy D. Buckler, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, he corner points mentioned in lines 1 and 2 above were, in a field survey on 6-18-80 I-9, 7-9, 1981, established, e-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations			
1 1 4	and rules therefore as required a Bureau of Land Management or and 5 above were, in a field survi	n the current manual of surve by a decree of a court of law.	ey instructions of the United S Furthermore, that the corner 19, found, recovered, rest	in conformance with regulations itates Department of the Interior, r points mentioned in lines 3, 4 tored, established or re-established ration for Land Surveyors or, by a
K-5	Sugar 12", N30°W, 30 lks, and Hemlock 18", S32°E, 36 lks.			
H-12	Sec. Cor. 25-36, T42- Spruce 5". N26°W. 1	1E and Sec's. 30-31, 6 lks. and Fir 8", 8	42-2 <b>E.</b> Bearings were 859 <sup>°</sup> W, <i>2</i> 7 lks.	
I <del>-9</del>	Sec. Cor. 22-23-26-27, set by John Mullett, D.S. in 1845. Bearings were: Sugar 14", N53°E, 16 lks. and Iron Wood 10", S75°E, 22 lks.			
K-5	his witnesses; NW Cor 35.2'. G.F.D.'s note to have been blased a	te monument at corner. Large Rock, N642 E is indicate orig. with with the street or st	r set by G.F. DeLamate, 108.9' and North Conesses. Found two Har	or. 6' long Rock, S8 <sup>o</sup> W,
K-12	Found 5/8" x 24" Iron limestone boulder, 36 swamp.	, set by G.F. DeLaMa "long, N24°E, 22.6"	ter, R.L.S. in 1947, t . Corner lies 20' Sou	by S.P.M. witnesses by a open of a low ridge and in
I <b>-</b> 9	Found 4" Concrete Mon monument.		. DeLaMater, R.L.S. in	
K-5	C. Description of monument for Re-marked witnesses: Corner lies 40' West	r corner and accessories estable 15" H. Maple, \$30 of a woods road.	lished to perpetuate locating the W, 7.81 & 11" H. Mapl	e position of the corner: Le, N27°W, 13.9'.
N-12 I-9	Placed 1" pipe with 4	," alum, cap at corne	st., 48.21.	"Cedar, N8°W, 29.0'& S38°E, 7.0'& & 6" H. Marle, N45°E, 68.6
		D. Buckler	7-16-	SATE OF MICH