

## MAR 2 0 2000

## SECTION

## LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

## **Mackinac County Remonumentation Corner**

N 78 W

N 51 E

04 lks

84.603

For corners in

Mackinac County	Located in:		Corner Code #
Public Land Survey	T <sup>2</sup> T T	12N R01E R R R R	C-11
zi i iopoiti poittioniii	S T S T	R R	
	S T	R R	

RECEIVED & FILED DIANE FRANKOVICH Mackinac county registed of deeds

FEB 2 5 2000

FM AA 71819119111912111213141510

Register of Deeds Stamp & File Number

4. Lot No.

, Recorded Plat

5. Private Claims


1, Neil E. Hill, in a field survey on 12-20-99, do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

		10" Aspen	N 72 E	09 lks
1990	Neil Hill MDOT recovered iron	n, set monument	box	
1996	Ronald Bischer	Fence Cor	Due S	44.25
	Fd 1/2" Rod in Mon Box	1⁄2" Rod	Due S	75.00'
	Liber E Page 044	Pwr Pole	N 18 W	34.70'

6" Cedar



ACCEPTED BY THE MACKINAC COUNTY SURVEY PEER GROUP AS THE OFFICIAL CORNER UNDER PA. 345 OF 1990 AT A MEETING 12-10-90 **HELD ON** 

No Subsequent Information

1845 GLO Notes J Mullett

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

6" Cedar

1999 Fd 1/2" rod and 2 witnesses Accepted corner location

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Corner is 1/2" rod with MDOT Cap #27447, in monument box Corner is 2.0' South of CL of M-134

Due S	75.00'
N 18 W	35.94'
Due S	65.08'
N 05 E	33.72
	Due S



Bearings are compass bearings, corrected for declination, all distances are to a double- head nail in the side of the witness object unless otherwise noted.

Date

21 2000 January

Surveyor's Michigan License No. 27447