

## LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

MAR 2 0 2000

SECTION

**Mackinac County Remonumentation Corner** 

For corners in

Mackinac County Located in: Corner Code # T42N R01E 1. Public Land Survey K-3 T R T R R T 2. Property Controlling T R S in Section S Т R S R 3. Miscellaneous Ţ R Property in Sec. S

accevea DIAME FRANKOVICH MACKINAC COUNTY REGISTER OF DESCO

FEB 25 2000

01:01:11:12:112:314:317

Register of Deeds Stamp & File Number


4. Lot No.

, Recorded Plat

5. Private Claims

I, Neil E. Hill, in a field survey on 12-20-99, do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and for that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.



A. Description of original monument and accessories and/or subsequent restoration:

1845 GLO	Notes J Mullett	14" Cedar 8" Cedar	S 45 E N 22 W	33 lks 10 lks
acce Set p	am Karr cod hub, pted location pipe cap #27450 · C Page 245	Pwr Pole Ancher Pole 6" B Fir "x" in Rock	N 45 E S 78 E S 58 W N 64 W	50.83' 35.53' 30.68' 88.05'

ACCEPTED BY THE MACKINAC COUNTY SURVEY PEER GROUP AS THE OFFICIAL CORNER UNDER PA. 845 OF 1990 AT A MEETING HELD ON er E udell

No Subsequent Information

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

1999 Fd pipe and 1 witness Accepted corner location Placed 4" Alum. remonumentation cap.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Corner is a pipe with 4" Alum remonumentation cap Corner is approximately at the intersection of CL of roads to the North and West, and in the Back slope of a drive to the East

Trans Pole	 30.59' 52.44'	(Face witness 6' tall steel pole)
Steel Post 5" Spruce	 11.00' 25.46'	(Face witness, 6' tall steel pole)



Bearings are compass bearings, corrected for declination, all distances are to a double- head nail in the side of the witness object unless otherwise noted.

Date

PS.BC

January 21 2000

Surveyor's Michigan License No. 27447

FORM APPROVED BY M-CHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1971 REVISED MAY 14, 1975 REVISED JAN., 1983 REVISED OCT., 1995