## MICHIGAN DEPARTMENT OF CONSERVATION

FORESTRY DIVISION

## LAND CORNER RECORD

T 42 NR 1 4.

			Mackinac	. <b>_</b>	COUNTY
DESCRIPTION	OF CORNER	Section Corn	er common to Sec.	<u>17-18-19-2</u>	<u> </u>
DESCRIPTION	OF CORNER	MONUMENT_	1" pipe with 4" b	rass cap	
WITNESSES 1	TO CORNER		S_17° W_ Marked "S 19 NBT	•	
		8" W. Pine	N 52° E Marked "S 17 NBT		<b>L</b>

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

Replaced Section Corner from W. Pine B.T. bearing N 38° W 13 links. Bottom of stump remaisn. Found part of notch and bearing blaze. Stump badly burned.

Found recent stake in place, also in clay soil found remains of older stake.

Corner lies on south edge of old E-W logging R.R. grade. This grade rums along line the entire mile east.

SURVEYOR'S SEAL

SIGNED BILLY D. SURVEYOR DATE 4/30/57