MICHIGAN DEPARTMENT OF CONSERVATION FORESTRY DIVISION

LAND CORNER RECORD

T 42 NR 1 Y

	Mackinac	COUNTY
DESCRIPTION OF CORNER	1/4 Corner between Sec. 's 8-17	
DESCRIPTION OF CORNER	MONUMENT_1" pipe with 4" brass	ceb
WITNESSES TO CORNER	8" Cedar S 48° V 57 Marked "1/4 S MBT" 6" Cedar S 50° E 62	linke
	6" Cedar 8 50° E 62 Marked "1/4 S NBT"	links
	MARKED "1/4 5 MDT"	

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

Re-established 1/4 Corner midway and on line between two Section Corners.

We evidence of original corner. Distance checks east to swamp edge.

SURVEYORS SEAL

SIGNED Silly & Buckler DATE 4/29/57 _