

MICHIGAN  
DEPARTMENT OF CONSERVATION  
FORESTRY DIVISION

LAND CORNER RECORD

T..42. NR 1 W. . .

..... Chippewa ..... COUNTY

DESCRIPTION OF CORNER Section Corner common to Sections 16, 17, 20, 21 . .

DESCRIPTION OF CORNER MONUMENT 1" pipe with 4" brass cap . . . . .

WITNESSES TO CORNER 14" W. Pine . . . . . S 48° W . . . . . 86 links . . . . .

12" W. Pine . . . . . S 41° W . . . . . 108½ links . . . . .

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

Replaced Section Corner from one W. Pine B. T., (stump down, burned)

Corner found while checking picket lines run by Wesly Lehman, District Forester.

Found 4 old stakes in soil.

Corner placed and witnessed October 4, 1956.

SURVEYORS SEAL

SIGNED Billy D. Buckler . . . . . DATE 10/15/56  
REGISTERED LAND SURVEYOR