JAN 21 1999

## LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

**SECTION** 

**Mackinac County Remonumentation Corner** 

For corners in

Corner Code # Located in: Mackinac County R01W 1. Public Land Survey T42N Т Ŕ R Т R Т R S Т 2. Property Controlling R S T in Section S Т R 3. Miscellaneous S R Property in Sec.

4. Lot No.

, Recorded Plat

5. Private Claims

I. Neil E. Hill, in a field survey on 12-21-98, do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:


1845	GLO Notes J Mullett	6" Maple 6" Beech	S 32 W N 48 E	5 lks 11lks
1994	R Bischer	Tel Pole	S 29 W	68.05'
	Set ½" Rod by	4" Maple	S 45 W	64.26
	Single proportion	3" Maple	S 67 W	73.45'
	Liber D, Page 263	3" Birch	S 88 W	75.83'

1997 R.S.Scott Associates Fd 1/2" Rod Remonumentation peer group held over corner due to lack of information

RECEIVED & FILED DIANE FRANKOVICH MACKINAC COUNTY REGISTER OF DEEDS

DEC 3 1 1998 PM 7 | 8 | 9 | 10 | 11 | 12 | 1 | 2 | 3 | 4 | 5 | 6

Register of Deeds Stamp & File Number



ACCEPTED BY THE MACKINAC COUNTY SURVEY PEER GROUP AS THE OFFICIAL CORNER UNDER PA. 345 OF 1990 AT A MEETING 12-04-98 NEH HELD ON

- B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:
  - 1998 Fd 1/2" re-rod in mon box severly bent and 3 witnesses Straightened corner from existing witnesses Accepted corner location Placed 4" Alum, remonumentation cap



C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Corner is a 1/2" rerod in mon box with 4" Alum, remonumentation cap Corner is on the CL of 3-Mile Rd

-			
½" re-rod	Due W	33.00'	
Pwr Pole	S 29 W	68.05'	(Pole cut off 4' high, witness nail in rear, NOT PK nail on roadside)
3" Maple	S 67 W	73.45'	
3" Birch	S 88 W	75.83'	

Bearings are compass bearings, corrected for declination, all distances are to a double-headed nail in the side of the witness object unless otherwise noted.

12-29-98 Date

Surveyor's Michigan License No. 27447