JAN 21 1999

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

SECTION

Mackinac County Remonumentation Corner

For corners in

Mackinac County Located in: , Corner Code # T42N R01W 1. Public Land Survey G-8Ţ R Т R R Т 2. Property Controlling S in Section Т R S R 3. Miscellaneous S T Property in Sec. S

4. Lot No. , Recorded Plat

5. Private Claims

I, Neil E. Hill, in a field survey on 12-21-98, do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and for that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

1845	GLO Notes J Mullett	12" W Pine 4" Fir	S 21 W N 19 E	09 lks 15 lks
1977	Larry Feindt	CL Road	Due E	6.5'
	Set 1" pipe by	Pwr Pole	S 45 W	43.5'
	Single proportion	12" Spruce	S 43 E	55.9'
	Liber A, Page 198	12" W Pine	N 40 W	68.2'

1997 R.S. Scott Associates Fd 1" pipe 6.35' West of CL of 3-Mile Rd Remonumentation peer group held over corner due to lack of information


RECEIVED & FILED DIANE FRANKOVICH

MACHINAC COUNTY REGISTER OF DEEDS

DEC 3 1 1998 AM PM 7|8|9|10|11|12|1|2|3|4|5|6

1

Register of Deeds Stamp & File Number



ACCEPTED BY THE MACKINAC COUNTY SURVEY PEER GROUP AS THE OFFICIAL CORNER UNDER P.A. 345 OF 1990 AT A MEETING HELD ON 12-04-98 USH

- B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:
 - 1998 Corner obliterated in road construction, no evidence remaining Placed corner midway and online between section corners North & South
- C. Description of monument for corner and accessories established to perpetuate locating the position of the corner

Corner is a ½" re-rod with 4" Alum, remonumentation cap in a Mon box Corner is approx 6.4' West of CL of 3-Mile Rd

8" Spruce N 63 E 51.77'
Pwr Pole S 40 W 43.85'
14" W Pine N 40 W 68.58
14" Spruce S 57 E 56.36



Bearings are compass bearings, corrected for declination, all distances are to a double-headed nail in the side of the witness object unless otherwise noted.

Date

Signed by Neil E. Hill P.S.

12-29-9

Surveyor's Michigan License No. 27447