JAN 21 1999

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

SECTION

Mackinac County Remonumentation Corner

For corners in

Mackinac County	Located in	•	Corner Code #
Public Land Survey	T T T T	42N R01W R R R	I-2
 Property Controlling in Section Miscellaneous Property in Sec. 	S T S T S T	R R R R	

4. Lot No. , Recorded Plat

5. Private Claims

I, Neil E Hill, in a field survey on 12-21-98, do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and for that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.


A. Description of original monument and accessories and/or subsequent restoration:

1845 GLO Notes James Mullett	20" Sugar	S 68 W	16 lks
	16" Sugar	S 67 E	39 lks
1984 William Karr Set 1" Rod Liber C, Page 62	10" Sugar 10" Sugar 10" Sugar C/L Gravel Rd	S 38 E N 56 E S 64 W East	31.14 ft 27.85 ft 61.94 ft 14 ft

RECEIVED & FILED DIANE FRANKOVICH MACKINAC COUNTY REGISTER OF DEEDS

DEC 3 1 1998 **PM** 7 8 9 1 0 1 1 1 2 1 2 3 4 5 6

Register of Deeds Stamp & File Number



ACCEPTED BY THE MACKINAC COUNTY SURVEY PEER GROUP AS THE OFFICIAL CORNER UNDER P.A. **3**45 OF 1990 AT A MEETING HELD ON 12-04-98 NEH

- B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:
 - 1998 Fd 1/2" re-rod and 2 witnesses and placed 4" Alum. remonumentation cap Accepted corner location
- C. Description of monument for corner and accessories established to perpetuate locating the position of the corner

Corner is a 1/2" re-rod with 4" Alum. remonumentation cap Corner is approx 14 feet East of the CL of gravel road Corner is over a culvert in a drive to the East

Pwr Pole S 50 W 18.39' Gate Post N 60 E 18" Maple S 50 E 39.12' 12" Maple N 15 E 41.90



Bearings are compass bearings, corrected for declination, all distances are to double-headed nail in the side of the witness object unless otherwise noted.

Signed by

12-29-98 Date

Surveyor's Michigan License No. 27447

FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1971
REVISED MAY 14, 1975
REVISED JAN., 1983
REVISED OCT., 1995