SECTION

MAR 2 0 2000

RELIANCE ENTATION

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

Mackinac County Remonumentation Corner

For corners in

Located in: Corner Code # Mackinac County 1. Public Land Survey T42N R01W K-10 T R T R T R S T R 2. Property Controlling S Т R in Section Miscellaneous S T R S Property in Sec.

4. Lot No.

, Recorded Plat

5. Private Claims

I, Neil E Hill, in a field survey on 12-20-99, do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and for that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

1845	GLO Notes James Mullett	10" Spruce 16" Cedar	S 75 W S 23 E	14 lks 13 lks
1979	Sherman Chamberlain (CA&E) Survey for E Rudd	14" Spruce Pwr Pole 6" Balsam	N 30 E N 65 W S 10 E	32.75' 82.17' 26.23'
1987	Neil E Hill Fd ½" Rerod Liber C Page 299	14" Spruce Pwr Pole Pwr Pole Pwr Pole	N 30 W N 65 W S 10 E N 80 E	32.75' 82.17' 26.23' 86.68'


RECEIVED & FILED

DIANE FRANKOVICH MACKINAC COUNTY REGISTER OF DEEDS

FEB 2 5 2000

AM FM 71819110111112111213141516

Register of Deeds Stamp & File Number



ACCEPTED BY THE MACKINAC COUNTY SURVEY PEER GROUP AS THE OFFICIAL CORNER UNDER PA. **3**45 OF 1990 AT A MEETING HELD ON

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

1999 Fd corner

Accepted corner location

Placed 4" Alum. remonumentation cap

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Corner is a 1/2" rod with 4" Alum. remonumentation cap

33.08 T Iron Due S 8" Spruce S 10 E 26.55' 8" Spruce 38.86' S 30 E 12" Cedar N 30 W 44.73



Bearings are compass bearings, corrected for declination, all distances are to a nail and tag in the side of the witness object unless otherwise noted.

Date

15,9c.

21 2000 January

Surveyor's Michigan License No.