

MAR 2 0 2000

SECTION

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

Mackinac County Remonumentation Corner

For corners in

Mackinac County

Located in:

Corner Code #

1. Public Land Survey

T42N R01E T42N R01W R Т R R T

WCMC A-12/13 WCMC M-12/13 ▶

2. Property Controlling in Section 3. Miscellaneous

Property in Sec.

S S Т R S R Т S R

#11

4. Lot No.

, Recorded Plat

5. Private Claims

I, Neil E. Hill, in a field survey on 12-20-99, do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and for that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

1845 GLO Notes William A Burt

40" Elm

S 10 W

45 lks

No Subsequent Information

ACCEPTED BY THE MACKINAC COUNTY

6

7

8

9

12 13

> SURVEY PEER GROUP AS THE OFFICIAL CORNER UNDER PA.

RECEIVED & FILED

DIANE FRANKOVICH MACKINAC COUNTY RECISTED OF DEEDS

FEB 2 5 2000

3[8[6]10]11[12]1[2]3]4[5]6

C D

Register of Deeds Stamp & File Number

۶ G Н \$3.44

K L ٠ ١

-(Sill

345 OF 1990 AT A MEETING

1-05 HELD ON

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

1999 No evidence of original or subsequent corners Drilled 1/2" rod and Cap #27447 in bit roadway online and at GLO distance from South

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Corner is a 1/2" rod with cap #27447 Corner is 2' East of CL of roadway

Pwr Pole S 20 E 65.20

18" Spruce 1/2" Iron

S 30 E Due N

61.05

203.99 No other witnesses available

neil e H25.

Land

Surveyor

No

Bearings are compass bearings, corrected for declination, all distances are to a double- head nail in the side of the witness object unless otherwise noted.

F. Will PS, R.C.

January 21 2000

Date

Surveyor's Michigan License No. 27447

C0009

ORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1971 REVISED MAY 14, 1975 REVISED JAN., 1983 REVISED JAN., 1983 REVISED OCT., 1995

1999-48