CONS. 4047 REV. 10/60

MICHIGAN DEPARTMENT OF CONSERVATION FORESTRY DIVISION

LAND CORNER RECORD

T. 42 N.R. 5-6W

		Mackinac Mackinac					_ COUNTY
DESCRIPTION OF CORNER _	Section corner for sections 6-7-1-12						
CORNER MONUMENT	l" pipe	with 4" brass	cap	· · · · ·			
DATE MONUMENT PLACED AN	WITNESSED	9-20-61 wi	th Hal	bach			
WITNESSES TO CORNER		9" Red Pine	(s 1	NBT)	N25°W	$34^{\frac{1}{2}}$ links	
N	<u></u>	7" Red Pine	(s 7	NBT)	S28°E	$27\frac{1}{2}$ links	
42+6		8" Red Pine	(s 6	N BT)	N70°E	48½ links	
CIRCLE CORNER REGISTERED	AND						

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was replaced as set by Marcus Schaaf, Registered Land Surveyor, found 2" iron pipe set by Schaaf; also found new witnesses as noted by Schaaf. Corner lies 2 chain S E of corner of USFS planting.

SURYEYOR'S SEAL

REGISTERED LAND SURVEYOR

Billy D. Buckler