

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T. 42N N.R. 6W


Mackinac COUNTY

DESCRIPTION OF CORNER North 1/8 corner between sections 17-18

CORNER MONUMENT 1" pipe with 4" aluminum cap.

DATE MONUMENT PLACED AND WITNESSED 5-2-62

WITNESSES TO CORNER..... 8" Hard Maple (BT) N9°W, 25 links



7" Beech (BT) S85°E, 52 links

Corner lies 58 links NE of center of road

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was placed midway between Section Corner to North and 1/4 corner to South.

SURVEYOR'S SEAL

SIGNED Billy D. Buckler DATE April 29, 1963
REGISTERED LAND SURVEYOR
Billy D. Buckler