

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T. 42N N.R. 6W


Mackinac COUNTY

DESCRIPTION OF CORNER 1/4 corner for sections 8 and 17

CORNER MONUMENT 1" iron pipe with 4" aluminum cap.

DATE MONUMENT PLACED AND WITNESSED 4-25-62

WITNESSES TO CORNER..... 12" beech (NBT 1/4 S) N70°W, 12 1/2 links



16" Beech (NBT 1/4 S) S24°E, 13 1/2 links

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was placed midway and on line between section corners. No evidence of original corner.

SURVEYOR'S SEAL

SIGNED Billy D. Buckler DATE July 19, 1963
REGISTERED LAND SURVEYOR
Billy D. Buckler