Coms. 4047 REV. 10/60

## MICHIGAN DEPARTMENT OF CONSERVATION FORESTRY DIVISION

## LAND CORNER RECORD

T. 42N M.R. 6W

Mackinac	COUNTY
1/4 corner for sections 7-18	
l" pipe with 4" aluminum cap.	
SSED 4-25-62	
9" Hard Maple (4S NBT) West 68 links	
8" Soft Maple (\$\frac{1}{4}S NBT) N 13°E, 22\frac{1}{2} links	
Squared and scribed 6" hard maple at corner.	
	1/4 corner for sections 7-18  1" pipe with 4" aluminum cap.  3SED 4-25-62  9" Hard Maple (\frac{1}{4}S \text{ NBT}) \text{ West } 68\frac{1}{2} \text{ links}  8" Soft Maple (\frac{1}{4}S \text{ NBT}) \text{ NBT}) \text{ N 13°E, } 22\frac{1}{2} \text{ links}

DESCRIPTION IN DETAIL AS TO NOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was re-established by single proportionate measure between two section corners.

SURVEYOR'S SEAL

SIGNED Silly Suckles DATE July 19, 1963

REGISTERED LAND SURVEYOR

Billy D. Buckler