

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T. 42 N.R. 6 W


Mackinac COUNTY

DESCRIPTION OF CORNER 1/4 corner for sections 5-8

CORNER MONUMENT 1" pipe with 4" brass cap

DATE MONUMENT PLACED AND WITNESSED 9-22-61

WITNESSES TO CORNER..... 14" W. Pine Stub ($\frac{1}{4}$ S NBT) N20°E 83 $\frac{1}{2}$ links



18" W. Pine Stub ($\frac{1}{4}$ S NBT) S75°W 105 links

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was re-established midway and on line between two section corners. No evidence of original corner.
Corner lies in south edge of lowland.

SURVEYOR'S SEAL

SIGNED Billy D. Buckler DATE March 14, 1962
REGISTERED LAND SURVEYOR

Billy D. Buckler