MICHIGAN DEPARTMENT OF CONSERVATION FORESTRY DIVISION

LAND CORNER RECORD

T. <u>42N</u> #.R. <u>6W</u>

	Mackinac	COUNTY
DESCRIPTION OF CORNER	East 1/8 corner between sections 8-17	
CORNER MONUMENT	l" pipe with 4" aluminum cap.	
DATE MONUMENT PLACED AND	WITNESSED <u>5-2-62</u>	
WITNESSES TO CORNER	. 4" Soft Maple (BT) N72°W, 51 links	
N8	4" Soft Maple (BT) N16°E, 31 links	
CIRCLE CORNER REGISTERED	AND	

DESCRIPTION IN DETAIL AS TO NOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was placed midway and on line between section corner to east and 1/4 corner to west.

SURVEYOR'S SEAL

REGISTERED LAND SURVEYOR BYILY D. Buckler