

MICHIGAN  
DEPARTMENT OF CONSERVATION  
FORESTRY DIVISION

# LAND CORNER RECORD

T. 42N N. R. 6W


Mackinac COUNTY

DESCRIPTION OF CORNER 1/4 corner between sections 16-21

CORNER MONUMENT Iron Drift Pin buried in road.

DATE MONUMENT PLACED AND WITNESSED 5-2-62

WITNESSES TO CORNER..... None available



CIRCLE CORNER REGISTERED

AND

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was recorded as set by D. Brotherton, Registered land surveyor, 1915.  
Corner lies in line with old road to south.

SURVEYOR'S SEAL

SIGNED Billy D. Buckler DATE April 29, 1963  
REGISTERED LAND SURVEYOR  
Billy D. Buckler