Cons. 4047 Rev. 10/60

MICHIGAN DEPARTMENT OF CONSERVATION FORESTRY DIVISION

LAND CORNER RECORD

T. 42N N.R. 6W

	Mackinac	COUNTY
DESCRIPTION OF CORNER _	West 1/8 corner between sections 10-15	
CORNER MONUMENT	1" pipe with 4" aluminum cap.	
DATE MONUMENT PLACED AND	WITHESSED 4-24-62	
WITHESSES TO CORNER	. 16" W. Pine Stump (BT) N12°W, 75½ links	
N 10	Corner lies 1 chain east of road	
CIRCLE CORNER REGISTERED	AND	

DESCRIPTION IN DETAIL AS TO NOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was placed midway between section corner west and 1/4 corner east.

SURVEYOR'S SEAL

SIGNED Silly Of Suchles

DATE April 26, 1963

Billy D. Buckler