Cons. 4047 Rev. 10/60

## MICHIGAN DEPARTMENT OF CONSERVATION FORESTRY DIVISION

## LAND CORNER RECORD

T. 42N N.R. 6W

		Mackinac	COUNTY
DESCRIPTION OF CORNER _	Section corner fo	or sections 3-4-9-10	
CORNER MONUMENT	1" pipe with 4" b	orass cap.	
DATE MONUMENT PLACED AN	D WITHESSED	_19-62	
	18" W. Pine (	S10 NBT) S10 E, 70 links	
N T			
10			
+		· · · · · · · · · · · · · · · · · · ·	<del> </del>
CIRCLE CORNER REGISTERE	AND		

DESCRIPTION IN DETAIL AS TO NOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was re-established using proportionate distance to corners east and west, and on line of blazes E-W. Found blazes to south of corner.

SURVEYOR'S SEAL

Billy D. Buckler