

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T. 42 N. R. 6-7 W


Mackinac COUNTY

DESCRIPTION OF CORNER 1/4 Corner between Sections 7 - 12

CORNER MONUMENT 1" Pipe with 4" Aluminum Cap

DATE MONUMENT PLACED AND WITNESSED December 14, 1963

WITNESSES TO CORNER..... 10" Hard Maple (1/4S NBT) S 24° W 39½ Links



12" Soft Maple (1/4S NBT) N 32° W 58 Links

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner re-established on line between Hemlock Line Tree to South and Section Corner to North. Found old blazes at corner.

SURVEYOR'S SEAL

SIGNED Billy D. Buckler DATE March 16, 1964
REGISTERED LAND SURVEYOR
Billy D. Buckler