LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, MICH. P.A.1970

MACKINAC, CO.	3 corners
FOR CORNERS OF -: LOCATED IN -:	CORNER CODE NUMBER
1. PUBLIC LAND SURVEY T. 42N S., R. 6W W.	6_SEC. 15
2. PROPERTY CONTROLISEC. 15. 42N N. 6W W. ING IN SECTION E.	9_SEC. 15
3. MISCELLANEOUS N. E. PROPERTY IN SECTION T. T. S., R. W.	13- SEC 15
4. LOT NO, RECORDED PLAT	
5. PRIVATE CLAIMS	REGISTER OF DEEDS STAMP AND FILING NUMBER
the corner points mentioned in lines 1 and 2 above were, in a fre-established, monumented, re-monumented, recovered or restand rules therefore as required in the current manual of survey Bureau of Land Management or by a decree of a court of law, and 5 above were, in a field survey on as expressed below and in conformance with the rules of the M Decree of a Court of law: A. Description of original monument and accessories and/or survey on a SEC. 15: North- EAst 1/16 Corner, Sec. 15: East 1/16 Corner, Sec. 15. South-East 1/16 Corner Sec. 15.	represed below and in combinative with regulation instructions of the United States Department of the Interior Furthermore, that the corner points mentioned in lines 3, 19, found, recovered, restored, established or re-established lichigan State Board of Registration for Land Surveyors or, by absequent restoration: 2. 15.
B. Description of corner evidence found and/or method applie 6_SEC. 15 Placed Corner at center of the 9_SEC.15: Placed Corner midway bet. Cent East 1/4 Corner. 13_SEC.15: Placed Corner at center of the	ter of Section and the
C. Description of monument for corner and accessories establing Placed 1" Pipe with 4" Aluminum Cap at a 6-SEC.15; Bearings;	
9_SEC.15, Bearings; 8" Soft Maple, N45'E	, 8.8° and 8° Hard Maple,
13_SEC15: Bearings: 8" Beach, N16'E, 1	
SIGNED BY Billy D. Byckler Suchle	
SURVEYOR'S MICHIGAN REGISTRATION NO.	SU.
FOR STATE AND UNITED STATES AGENCIES:	
CHIEF OF SURVEY PARTY	DATE
APPROVED AND SIGNED BYMICHIGAN REGISTERED LA	DATE

SURVEYOR'S MICHIGAN REGISTRATION NO.___