LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, MICH. P.A.1970
Mackings Co. 2 Corners.

FOR CORNERS OF -:	LOCATED IN-:	CORNER CODE NUMBER	
1. PUBLIC LAND SURVEY	T S., R W.	8_Sec.14	
2. PROPERTY CONTROLL- ING IN SECTION	. ,T. 42 N. R. 6 V.	4_Sec.14	
3. MISCELLANEOUS PROPERTY IN SECTION	,TS., RE.		
4. LOT NO , REC	CORDED PLAT		
5. PRIVATE CLAIMS		RE	GISTER OF DEEDS STAMP AND FILING NUMBER
I,			
A. Description of original monument and accessories and/or subsequent restoration:			
8-Sec.14 West 1/16 Corner of Section 14.			
4-Sec.14 Northwest 1/16 Corner of Section 14.			
B. Description of corner evidence found and/or method applied in restoring or re-establishing corner: 8-Sec.14 Corner established midway between West 1 corner and Center of Section. 4-Sec.14 Corner established at center of the Northwest Quarter Section.			
C. Description of monument for corner and accessories established to perpetuate locating the position of the corner: Placed 1" pipe with 4" aluminium cap at both corners.			
		•	
8-Sec.14 Bearings:	14" Beech, N51°E, 3 12" Beech, S60°E, 1	3.7' and 8" Beech, S65 W	, 8.7° and
	12" Beech, S60°E, 1	19.2'. 1. 29.9' and 6" S. Maple	
SIGNED BY	12" Beech, S60 E, 1 8" Soft Maple, S60°E, 6" S. Maple, N59°E,	19.2'. 3. 29.9' and 6" S. Maple 2.3'. Marker Date 11-78	
SIGNED BY	12" Beech, S60 E, 1 8" Soft Maple, S60 E, 6" S. Maple, N59 E, ckler REGISTRATION NO. 888	19.2'. 3. 29.9' and 6" S. Maple 2.3'. Marker Date 11-78	N53°W, 11.3° and STE OF MAC; BILLY D BUCKLER LAND
SIGNED BY Billy D. Bu SURVEYOR'S MICHIGAN I	12" Beech, S60 E, 1 8" Soft Maple, S60 E, 6" S. Maple, N59 E, ckler REGISTRATION NO. 888	19.2'. 19.2'. 2.3'. Maple 2.3'. DATE	N53°W, 11.3° and STE OF MAC; BILLY D BUCKLER LAND
SIGNED BY Billy D. Bu SURVEYOR'S MICHIGAN I	12" Beech, S60 E, 1 8" Soft Maple, S60 E, 6" S. Maple, N59 E, ckler REGISTRATION NO. 888; STATES AGENCIES:	19.2'. 1. 29.9' and 6" S. Maple 2.3'. DATE	N53°W, 11.3° and STE OF MAC; BILLY D BUCKLER LAND